

Technical Report Documentation Page

1. REPORT No.

Lab. Proj. Auth. 71-R-6244

2. GOVERNMENT ACCESSION No.**3. RECIPIENT'S CATALOG No.****4. TITLE AND SUBTITLE**

Investigation of the Comparative Corrosion of Aluminum and Steel Corrugated Metal Pipes in Similar Environments

5. REPORT DATE

September 1962

6. PERFORMING ORGANIZATION**7. AUTHOR(S)**

Maxwell, W.S. and R.F. Stratfull

8. PERFORMING ORGANIZATION REPORT No.

Lab. Proj. Auth. 71-R-6244

9. PERFORMING ORGANIZATION NAME AND ADDRESS

State of California
Department of Public Works
Division of Highways
Materials and Research Department

10. WORK UNIT No.**11. CONTRACT OR GRANT No.****13. TYPE OF REPORT & PERIOD COVERED****12. SPONSORING AGENCY NAME AND ADDRESS****14. SPONSORING AGENCY CODE****15. SUPPLEMENTARY NOTES****16. ABSTRACT**

I. Introduction

At the present time the California Standard Specifications specify that only tile, steel and concrete piping may be used for highway drainage structures. Manufacturers are now producing aluminum CMP and the Bureau of Public Roads and the California Division of Highways are cognizant of the possibility of an economic or engineering advantage in the use of the new material.

The test program was initiated on March 31, 1961, under Laboratory Project Authorization 71-R-6244 and the cost is borne by the California Division of Highways and the Bureau of Public Roads. This test will attempt to determine if there are limitations with respect to corrosion and abrasion, on the use of aluminum CMP for highway drainage structures. It should be noted that the test sites contained in this program are among the most corrosive and abrasive to metal culverts that have been found in the experience of the California Division of Highways.

17. KEYWORDS**18. No. OF PAGES:**

28

19. DRI WEBSITE LINK

<http://www.dot.ca.gov/hq/research/researchreports/1961-1963/62-15.pdf>

20. FILE NAME


62-15.pdf



STATE OF CALIFORNIA
DEPARTMENT OF PUBLIC WORKS
DIVISION OF HIGHWAYS

INVESTIGATION OF THE COMPARATIVE CORROSION
OF
ALUMINUM AND STEEL CORRUGATED METAL PIPES
IN SIMILAR ENVIRONMENTS

September 1962



62-15

State of California
Department of Public Works
Division of Highways
Materials and Research Department

September 1962

Mr. F. N. Hveem
Materials & Research Engineer
Division of Highways
Materials and Research Department
Sacramento, California

Lab. Proj. Auth.
71-R-6244


Dear Mr. Hveem:

Submitted for your information is the first progress
report on an:

INVESTIGATION OF THE COMPARATIVE CORROSION
OF
ALUMINUM AND STEEL CORRUGATED METAL PIPES
IN SIMILAR ENVIRONMENTS

Study made by Structural Materials Section
Under the direction of. J. L. Beaton
Work Supervised by. R. F. Stratfull
Report prepared by. W. S. Maxwell and R. F. Stratfull

Very truly yours,


J. L. Beaton
Supervising Highway Engineer

WSM/RFS: 1k

TABLE OF CONTENTS

I.	INTRODUCTION
II.	CONCLUSIONS
III.	ENVIRONMENTAL CONDITIONS
IV.	INSTALLATION METHODS
V.	CURRENT TEST RESULTS
VI.	APPENDIX
	Table 1 Test Results
	Table 2 Inspection Results
	Table 3 IV-SC1-5-C Inspection Results
	Exhibit 1 II-Sha-3-13
	Exhibit 2 III-But-21-B
	Exhibit 3, 4, & 5 IV-SC1-5-C
	Exhibit 6 Drawing of IV-SC1-5-C Installation
	Exhibit 7 X-SJ-53-C
	Exhibit 8 & 9 XI-Imp-187-F
	Exhibit 10 & 11 XI-SD-2-Natl City
	Exhibits 12 through 17 are photos showing the results of environmental exposure.

I. INTRODUCTION

At the present time the California Standard Specifications specify that only tile, steel and concrete piping may be used for highway drainage structures. Manufacturers are now producing aluminum CMP and the Bureau of Public Roads and the California Division of Highways are cognizent of the possibility of an economic or engineering advantage in the use of the new material.

The test program was initiated on March 31, 1961, under Laboratory Project Authorization 71-R-6244 and the cost is borne by the California Division of Highways and the Bureau of Public Roads. This test will attempt to determine if there are limitations with respect to corrosion and abrasion, on the use of aluminum CMP for highway drainage structures. It should be noted that the test sites contained in this program are among the most corrosive and abrasive to metal culverts that have been found in the experience of the California Division of Highways.

II. CONCLUSIONS

A. At the abrasion test site, the following conclusions appear warranted:

1. The aluminum pipe is not as abrasion resistant as the steel, and cannot be considered as an equal to steel in this respect.
2. Rivets should be placed in the valleys of the corrugations for all pipe no matter what material is used in its fabrication.
3. Asphalt is better in abrasion resistance as a pipe invert paving material than is concrete.
4. Asbestos bonding improves the abrasion resistance of an asphalt coated pipe.

B. At the corrosion test sites, the following apply:

1. In the locations of acidic soils and waters, the aluminum pipe is not economically superior to steel in corrosion resistance (Neither uncoated steel nor aluminum is satisfactory for use as culvert material at these locations)
2. The comparative corrosion resistance of aluminum to steel at all other sites (see B-1) cannot be determined at this time as both have had a nominal amount of corrosion attack.

III. ENVIRONMENTAL CONDITIONS

At each test site soil and water samples were obtained and chemically analyzed by the Materials and Research Department. The test results are included on Table 1. From our Test Method No. Calif. 643-A, the soil resistivity and the pH readings were used to determine the relative corrosivity of the test locations.

The abrasion test site was chosen because the reinforced concrete box at this location has required repair of the invert twice in ten years of service.

It should be noted that the test sites utilized in this study are probably the most aggressive sites in which culverts can be exposed.

IV. INSTALLATION METHODS

All test pipes were installed by the maintenance forces in each District. Generally, the pipes which were installed in the same channel were physically separated by a distance of approximately 3" between the abutting ends. Then a 1/8" thick neoprene gasket was used as an electrical insulating material between the pipe coupler and the pipes. After the neoprene gasket was in place, a bituminous coated steel coupler was installed.

The purpose of the gasket and coated coupler was to prevent galvanic corrosion of the aluminum. When aluminum and steel are electrically connected in an electrolyte such as soil, an electrical current will flow and cause accelerated corrosion of the aluminum. The two test metals were electrically separated by space or mechanical means in all locations except at the abrasion test site (IV-SC1-5-Sta 250+25, Br. #37-165). The pipes were not electrically separated at the abrasion test site as the possibility of galvanic corrosion is considered to be negligible, the reason being that water is present in the culvert only during periods of flow. This is approximately 3 to 6 times per year.

The details of the installation of the test pipes are shown by Exhibits 1 through 11.

V. CURRENT TEST RESULTS

Several inspections have been conducted at each test location. The results of the last inspection have been noted on Tables 2 and 3.

At the acid ground water test site in II-Sha-3-B, a section of aluminum CMP approximately 5" x 10" was cut from the invert after 56 days of exposure. A photo of this section of aluminum is shown on Exhibit 12 and represents the result of corrosion after 56 days of exposure.

The aluminum culvert in the abrasion test site requires repair due to the excessive metal loss of the rivets. The aluminum section should be repaired with bolts to prevent the loss of the plate. At the abrasion test site the apparent order of abrasion resistance is as follows, with number 1 being the best:

1. Asbestos bonded asphalt paved CMP
2. Asphalt dipped paved invert CMP
3. Galvanized steel CMP
4. Aluminum CMP
5. Concrete

At the corrosion test sites of high acidity, the aluminum did not appear to have better corrosion resistance than steel.

At the alkaline and sea water sites, the aluminum and steel were moderately affected by corrosion. The degree of corrosion has been nominal in both cases and will require additional study.

TABLE 1

TEST RESULTS

Locations	II-Sha-3-B Nr. Redding	III-But-21-B Nr. Oroville	IV-SCL-5-C Nr. Los Gatos	X-SJ-53-C Nr. Rio Vista	XI-SD-NatCity at Sweetwater Bridge	XI-Imp-187-F at Salton Sea
Installation Date	11-16-61	8-21-61	10-19-61	8-16-61	9-26-61	9-29-61
Avg. pH	3.3	2.7	7.7	4.5	6.3	8.3
Avg. Resistivity	650	165	3500	620	973	39
*Avg. Yrs.	Less than 5 yrs.	Less than 5 yrs.	49 years	Less than 5 yrs.	17 yrs.	Less than 5 years
Na + K (as Na) PPM	14	7	65	178	12,300	99,740
Ca PPM	44	266	102	65	170	12,300
Mg PPM	88	328	19	26	504	2,170
CO ₃ PPM	Nil	Nil	204	Nil	Nil	Nil
HCO ₃ PPM	Nil	Nil	Nil	9	170	180
CL PPM	Nil	50	516	144	14,920	41,520
SO ₄ PPM	996	13,800	132	356	2,220	7,920

A1 CMP Made of Alloy Clad MG-11a-H34

Galv. Steel CMP Made of Copper bearing steel with galvanized coating

*Estimated years to perforation of 16 gage steel CMP. Test Method Calif. 643-A

TABLE 2

INSPECTION RESULTS

Observations were made on both the soil and interior surface of the piping. The results of the last inspection are as follows:

Locations	Installation Date	Date of Last Inspection	Days of Exposure	Results of Last Inspection Aluminum	Steel
II-Sha-3-B Nr. Redding	11-16-61	4-23-62	157	Perforated Invert	No Perforation
III-But-21-B Nr. Oroville	8-21-61	4-24-62	266	Perforated Invert	Perforated Invert
X-SJ-53-C Nr. Rio Vista	8-16-61	4-24-62	271	Pit + .005" in one spot	No rust observed
XI-SD-2-Natl. City at Sweetwater Br.	9-26-61	4-30-62	215	Pit approx. .005+"	No rust observed
XI-Imp-187-F at Salton Sea	9-29-61	4-30-62	212	Pit approx. .002+" (soil side)	Rust just beginning (soil side)

TABLE 3

DISTRICT IV INSPECTION RESULTS

AT 187 DAYS OF EXPOSURE

Installation Date 10-19-61
Date of last Inspection 4-25-62

IV-SC1-5-C

Concrete
(Upstream)

Spalling of upstream concrete floor \pm 6" back of original line of concrete. Grooves about $\frac{1}{2}$ " deep in concrete floor through the aggregate.

Aluminum

Dents about $\frac{1}{4}$ " deep in about 10 locations. Nicks about $1/32$ " deep in approx. 25 locations. Aluminum rivets have lost approx. $\frac{1}{2}$ of their original metal thickness. Some rivets have severely deformed to the point that the line of demarcation between rivet and culvert metal are hardly visible. There is evidence of plastic flow of the aluminum culvert metal due to abrasion.

Galvanized Steel

No dents or noticeable nicks on steel surface. Zinc has been abraded from the steel in some areas. Rounding of upstream surface of rivets, but no structural problems. There is abrasion of steel, but quantity of steel loss cannot be estimated.

Asbestos Bonded
Paved Invert

Evidence of severe abrasion such as gouging and grooving, etc. No spalling of paving to metal surface. Paving intact as protective coating and no chips of asphalt in the dipped section of the pipe.

Asphalt Dip
Paved Invert

Chipping of asphalt in dipped section of pipe. Paved invert abraded in several locations, but still satisfactory as a protective coating.


Concrete
(Downstream)

Downstream concrete abraded about $\frac{1}{2}$ " deep in several locations (3 or 4) through the aggregate.

II-Sha-3-B
Rt. of Sta. 265




Excavating backfill
for culvert installa-
tion.




Note neoprene gasket
extending past edge
of coupler.




Backfilling over
the two CMPs.



Assembling of CMPs in
excavated trench



Placing coupler over
neoprene gasket




Backfill was obtained from
dark areas in face of
nearby cut



Placing backfill over piping



Backfilling over piping



Completed installation



Bolting walers to walls and floor
of RCB for CMP anchoring.



Completed waler installation.



Interior view of completed installation.
Note:


1. Steel channel used to anchor
CMP to waler.
2. End of white asbestos rope
hanging down at left; at
this point is a water-tight
lap joint.

IV-SC1-5-C
Sta. 250+25
Br. #37-165


EXHIBIT 4



Upstream end of RCB



Note roughness
of concrete floor
at end of waler.



Note irregularities
of concrete floor
under waler.

IV-SC1-5-C
Sta. 250+25
Br. #37-165





Upstream view of jetting
sand backfill under completed
sections of metal CMPs.



Upstream view of completed
installation in RCB.
Concrete apron starts inside
RCB approx. 50' from entrance.

Diagram illustrating the detail of a water tight joint at the laps of metal test sections (Detail A). The joint is sealed using a 3/4" asbestos rope, a 14 gage CMP (Cement Mortar Plaster), and a road oil sealer. The dimensions shown are 8" for the width of the joint and 12" for the length of the joint.





Placing neoprene gasket and
lower section of coupler



Placing top section
of coupler




Heavy equipment pulling a hand
operated scoop through ditch.



Lowering pipes into
ditch with rope.




Backfilling over piping




Completed installation


Obtaining backfill
material in field
adjacent to CMP
installation




Pipes separated
approximately 5'
and placed in ditch,
ready for backfill.
The pipes were not
connected with a
coupler.



Backfilling over
the galvanized CMP




XI-Imp-187-F
50' \pm Lt. of Sta. 498⁺



Note damaged end of
aluminum CMP due to
handling.



Compacting backfill
over CMP.



Completed
installation.

XI-SD-2-Nat. City
Approx. 20' Lt. of
Bent 5 of Br. #57-245,
Sweetwater Creek


EXHIBIT 10



Excavation along bank
of Sweetwater River
for CMP installation.




Excavating area for
CMP installation.




Note damaged areas
on aluminum CMP
due to handling.

XI-SD-2-Nat. City
Approx. 20' Lt. of
Bent #5 of Br. #57-245,
Sweetwater Creek


EXHIBIT 11



Note damaged
surface of alum.
CMP due to
handling



End view of
completed
installation
at low tide.



View of completed
installation taken
from Sweetwater Cr.
Br. #57-245-L at
high tide.




This sample was taken from the invert of alum. CMP
after 56 days of acid exposure. Invert perforated
at 157 days of exposure.

II-Sha-3-B
Rt. of Sta. 265

EXHIBIT 13




Galvanized CMP after 157 days of acid exposure. Invert not perforated.



Alum. CMP after 157 days of acid exposure.
Note: Perforations on invert of alum. CMP.

III-But-21-B
Rt. of Sta. 594†

EXHIBIT 14



Galvanized steel CMP after 266 days of acid exposure. Invert perforated.



Aluminum CMP after 266 days of acid exposure. Invert perforated.


IV-SC1-5-C
Sta. 250+25.
Br. #37-165

EXHIBIT 15



187 days of
abrasive exposure

Upstream end of test site. Concrete apron
abraded approximately 0.5 inches in depth.




Note abrasion of aluminum rivets and
denting of the surface of the pipe.



Invert of galvanized steel CMP.
Note: Anchor bolt and rivets.

IV-SC1-5-C
Sta. 250+25
Br. #37-165

EXHIBIT 16



187 days of
abrasive exposure

Bottom and side of asphalt dipped paved
invert pipe. Note chipping of asphalt
above paved invert. Paving is intact.




Invert of asbestos bonded paved
invert pipe and concrete test
section at downstream end of test
site. Concrete abraded approxi-
mately 0.5 inches in depth.



Invert of asbestos bonded paved
invert pipe. Paving is intact.
Note: anchor bolt.


XI-SD-2-Nat. City
Approx. 20' Lt. of Bent #5
Br. #57-245. Sweetwater Cr.

EXHIBIT 17



215 days of
exposure.

Aluminum CMP. Minor pitting of surface.



Galvanized steel CMP. Galvanizing is intact.